## **BUILDING SAFETY CERTIFICATE**

· No.	Dated:
Cer	tified that the existing building AADESHWAR ACADEMY at HALBAKACHORA, ADAWAL,
	SDALPUR DIST. BASTAR comprised of GF/ FF/ SF owned/occupied by
AA	DESHWAR ACADEMY have complied with the Building safety requirements in accordance
wit	National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on 20 3 2023 (date of inspection) in
the	Cresence of Principal and Staff and that the building/premises is fit for occupancy upto
ŧ O	years in accordance with rule and subject to compliance of the
, D	ued on 21/3/2000 at 11.0 Am by
tre.	Signature with Seal :Executive Engineer Name : P.W.D. North Bastar Dn. No1 अक िमांग विभाग (भ/स) उप-संभाग क्र0-2, जगदलपुर Name & Address of Department/ Office: (Assistant Engineer & above officer of concerned Govt. Department only)